

Oil Field Environmental Incident Summary

Incident: 20160805115508 **Date/Time of Notice:** 08/05/2016 11:55
Responsible Party: ENERGYQUEST II, LLC
Well Operator: ENERGYQUEST II, LLC
Well Name: BERTINUSON 1-30
Field Name: PATENT GATE **Well File #:** 9300
Date Incident: 8/4/2016 **Time Incident:** 15:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 100 **Sec:** 30 **Qtr:** SE NW
Location Description: Lat 47.867155, Long -103.526465

Submitted By: Larry Davis **Received By:**

Contact Person: Justine Detienne
4526 RESEARCH FOREST DR
SUITE 200
THE WOODLANDS, TX 77381

General Land Use: Well/Facility Site **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Unknown		Reported to NRC: No	
Spilled	Units	Recovered	Units

Oil

Brine

Other

Description of Other Released Contaminant:

Embers from flare.

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

No immediate risk beyond dangers of fire and smoke. Fire department on location.

Areal Extent:

About 200 feet by 150 feet. Burn area stopped at creek.

Potential Environmental Impacts:

None; no petroleum products or produced water were released.

Action Taken or Planned:

All equipment shut-in to terminate source of fire. Fire department extinguished grass fire.

Wastes Disposal Location:

Agencies Involved: Local Fire Department
McKenzie County Emergency Management

Updates

Date: 8/8/2016 **Status:** Reviewed - Follow-up Required **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, it was unknown whether the release was contained. Further follow-up needed.

Date: 8/11/2016 **Status:** Inspection **Author:** Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived on site at 11:09 a.m.; weather was sunny. The fire damage extends along the south of the pad to the dry creek. The grass looked burnt; however, it did not look to have any contamination. Check for vegetation at a later date.